

OUT58968

P 010017Z

FM NPIC WASH DC

TO AIG NINE SEVEN SIX

RUEKDA/DIA PRODCEN

RUEKDA/NIC

BT

C O N F I D E N T I A L CITE NPIC 7631.

INITIAL SCAN BY NPIC OF MISSION [REDACTED]

[REDACTED] REVEALS THAT LAOS ROUTE 96 IS UNSERVICEABLE AT 1525N 10700E. 45

TWO LARGE WASHES HAVE RENDERED IMPASSABLE TO VEHICLES APPROXIMATELY 6

350 YARDS OF THE ROAD FROM UTM YC149062 TO UTM YC149065, HOWEVER 7

A WELL USED TRAIL IS OBSERVED EXTENDING ALONG THE ROAD ALIGNMENT.

WEATHERING HAS ALSO CAUSED THE ROAD EMBANKMENT TO COLLAPSE AT UTM

YC147069, RENDERING THE ROAD IMPASSABLE AT THAT POINT. (BB)

MAP REF: UTM COORDINATES FROM AMS SERIES L7012, SHEET 6457111

GEOGRAPHIC COORDINATES FROM USATC SERIES 200, SHEET 0738-5HL

GP-1

C O N F I D E N T I A L

-END OF MESSAGE-

1 JUL 1966

DISTRIBUTION 7

Cy No.	Office	Action
1	File	
2	OS 19	
	ADMIN	
	SEC BR	
	P & DS	
3	CGD	
	IPD	
	PD	
	ESD	25X1
	ESD-ICB	
	HD	-25X1
	AD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy

Sanitized X

25X1

read by  
Dir  
Spec Dir  
1 July 1966  
He B

CONFIDENTIAL

25X1